

SECTION C (30 marks)

Answer any two questions from this section.

- 12 Figure 7 shows the three views of a machined block drawn in first angle projection. Draw, FULL SIZE, the block in isometric projection taking corner "Y" as the lowest point (15 marks)




Fig. 7